

## Firmware Updates

For more information, contact our team on - [technical.support@sonifex.co.uk](mailto:technical.support@sonifex.co.uk)

DHY-04G/HD Firmware Versions		
Version	Changes	Description
1.16	Alterations	Added LED speed indication for the new hardware
1.16	Alterations	Software package update to allow for the above
1.15	Alterations	Fixed bug refresh web page drops speed dialled call or incoming call
1.14	Alterations	Set dialler page as default when logging in at level 1
1.13	Alterations	Added option to hide memory dial numbers on main/dialler web pages
1.13	Alterations	Added option to auto logout level 2 users only
1.13	Alterations	Increased font size and added colours for call status in main/dialler pages
1.12	Alterations	Updated the help text
1.11	Alterations	Added the ability to send DTMF tones throughout the duration of a call, via online keypad or DHY-04RC hardware keypad
1.11	Alterations	Added 'DTMF Pin' field and 'Enable Auto Send of DTMF Pin' checkbox on 'Config' webpage
1.11	Alterations	Added 'Auto Redial Number' field and 'Enable Auto Redial' checkbox on 'Config' webpage
1.11	Alterations	Modified 'Dialler' webpage to show name for saved speed dial number next to corresponding button
1.11	Alterations	Added 'Factory Reset' button to 'Update' webpage
1.10	Alterations	Serial error response codes changed to decimal
1.10	Alterations	Initial 'v' within "VER:" and "BSV:" command response deleted
1.10	Alterations	Command "TEL:" now working properly
1.09	Alterations	Fixed bug causing lock up or undesired dropping of calls
1.09	Alterations	GPO Remote output functions correspond to selection on web server
1.08	Alterations	Fix missing 'Drop Call' from webpage when HD calls are made
1.05.66	Alterations	New range and threshold for DTMF Detect
1.05.66	Alterations	Changes for HD call states to show call quality
1.04.65	Alterations	Updated code to handle SIM Access Code
1.04.65	Alterations	DHY-04 Dialler page fix
1.04.64	Alterations	Fix dialling bug when no 'w' in dial string
1.04.63	Alterations	Updated code to handle SIM Access Code
1.04.63	Alterations	Factory reset after 3 resets each within 5–10 secs
1.04.63	Alterations	Dial out supports DTMF send after 'w' in string
1.04.63	Alterations	DTMF Send now via AT+_VTS=string command
1.04 Module	Alterations	Modified to allow for HD Voice Messaging