

Firmware Updates

For more information, contact our team on - technical.support@sonifex.co.uk

RB-VHDMA8, RB-VHEMA8, RB-VHCMA4 & RB-VHCMD16 Versions for units running V2.X.X Firmware Versions		
Version	Changes	Description
V2.1.3 / FPGA V2.1.0	Added	Support for updated component
V2.1.1 / FPGA V2.1.0	Fixed	Bug with setting of channel status for the analog inputs
V2.1.1 / FPGA V2.1.0	Fixed	Channel mapping bug for the channel status info
V2.1.0 / FPGA V2.1.0	Added	New option – Embed insert allows inserting channels to existing groups
V2.0.5 / FPGA V2.0.4	Fixed	Bug with reading setting of control mode on startup
V2.0.4 / FPGA V2.0.4	Added	Front panel lock persistence option
V2.0.4 / FPGA V2.0.4	Added	Front panel lock settable via front panel (hold bank, group, status buttons for 5 seconds)
V2.0.2 / FPGA V2.0.4	Changed	Reduced default front panel LED brightness slightly
V2.0.2 / FPGA V2.0.4	Added	Front panel brightness control via remote control
V2.0.2 / FPGA V2.0.4	Fixed	Audio output freeze when SRC disabled and input loses lock
V2.0.2 / FPGA V2.0.4	Added	Optimized internet checksum routine
V2.0.2 / FPGA V2.0.4	Fixed	Bug in video delay control
V2.0.2 / FPGA V2.0.4	Added	Increased delay width to allow for SD line delay
V2.0.1 / FPGA V2.0.3	Release	Initial release.