

Firmware Updates

For more information, contact our team on - technical.support@sonifex.co.uk

CM-TB8 Firmware Versions			
Version	Date	Changes	Description
V1.1.6	14/09/2017	New/Changed	Added support for new flash device SST26VF032B. Increased size of web page generation buffer to prevent overflow.
V1.1.5	27/02/2017	Changed	Changed IP address default to 0.0.0.0 when DHCP enabled as some switches fail to respond when a static IP address has already been assigned.
V1.1.4	27/06/2016	Changed	Changed GSM initialisation to include USIM application for newer module firmware revisions that fix network registration failure for some SIMs.
V1.1.3	13/08/2015	Fixed	Text error on load settings webpage.
V1.1.2	05/08/2015	New/Fixed	Added group talk exclusive mode option. Fixed reset config to defaults on power up.
V1.1.0	29/09/2014	Changed	Changed GSM network registration check to include roaming option.
V1.0.9	03/04/2014	Changed	GSM and PSTN web page changes.
V1.0.8	31/03/2014	New/Changed	Added audible call end signal with option on GSM web page. Added dynamic info, call control, call logs, and module reset to GSM web page.
V1.0.7	30/01/2014	Fixed/Changed	Fixed factory remote commands. Changed write serial number command to allow TL numbers.
V1.0.6	19/12/2013	New/Changed	Added support for GSM2 expansion card. Added firmware validity check when updating. Increased web page update to 27 seconds after firmware update.
V1.0.5	20/05/2013	Fixed	Various bug fixes and changes for PSTN2 expansion card.
V1.0.3	05/02/2013	Fixed	Fixed bug saving ethernet options by removing packed attribute.
V1.0.2	11/12/2012	New/Fixed	Infrared receiver test added to test mode 2. Added reset config defaults and reset talk level commands.
V1.0.1	10/12/2012	Changed	LED Test mode changed to illuminate level LED 1 red on start. Removed amber cycle from LED Test mode.
V1.0.0	07/12/2012	New	Initial release.