

Firmware Updates

For more information, contact our team on - technical.support@sonifex.co.uk

RB-FS82/42 Firmware Versions		
Version	Changes	Description
V1.13	Fixed	CAL command response (for production test)
V1.12	Fixed	Correct brightness for new LEDs
V1.11	Fixed	Dual DC supply version when using positive ground supply
V1.09	Fixed	Dual DC supply version: incorrect under-volt alarm threshold
V1.09	Improved	PSU voltage calculations and calibration
V1.09	Fixed	DC input 1 down trap never called
V1.07	Added	Standby usage option
V1.07	Added	Local/remote switching options
V1.07	Added	Extra SNMP functionality
V1.07	Improved	Optimised mDNS implementation
V1.02	Fixed	Addressing Mode Status display bug
V1.02	Added	LED flash to indicate a Factory Reset
V1.02	Added	Explicit warnings for Address Mode changes
V1.02	Added	GPI Alarm pin active level selection option (Configuration → Channels webpage)
V1.01	Release	Initial release