

## Firmware Updates

For more information, contact our team on - [technical.support@sonifex.co.uk](mailto:technical.support@sonifex.co.uk)

RB-IPE Firmware Versions		
Version	Changes	Description
V1.14.1	Added	Support for new flash device
V1.14.1	Fixed	Internal bug fixes
V1.13	Fixed	ADC clocking bug
V1.13	Fixed	Possible missing GPI automatic update bug
V1.13	Added	Analogue input calibration options to webserver
V1.13	Added	Analogue input calibration commands to command interface
V1.10	Fixed	Factory reset procedure bug
V1.10	Added	Notification webpage during refresh when browsing for local IPEs
V1.09	Fixed	Double response bug for ADC command
V1.08	Fixed	Webserver bugs including Analogue Outputs "Mapped to" setting
V1.08	Improved	Tooltip text on webserver
V1.08	Fixed	Connected LED behaviour bug