

## Firmware Updates

For more information, contact our team on - [technical.support@sonifex.co.uk](mailto:technical.support@sonifex.co.uk)

RB-TGHD Firmware Versions		
Version	Changes	Description
V1.011	Fixed	Fixed a bug where a channel with multiple steps fails to wrap correctly.
V1.010	Added	Added option to auto-start the selected sequence when the unit powers up.
V1.009	Added	Added delay prior to sync initialisation to allow card to boot reliably.
V1.007	Fixed	Fixed bug where user sequence failed to output correctly on all channels, with no tone interruption for channels that wrap.
V1.006	Fixed	Fixed bug where sequence select button caused unit crash when selecting user sequence.
V1.005	Added	Added frequency and amplitude control for each step in user sequence (requires tghd.sci v1.0.2 or later).
V1.001	Alterations	UART timeout changed to compensate for USB-serial converters.
V1.000	Release	Initial release.