

Firmware Updates

For more information, contact our team on - technical.support@sonifex.co.uk

S1 Firmware Versions		
Version	Changes	Description
V1.39	Fixed	Fix for Split Cue/PFL and Guest Mic Auto PFL button lock with SCi.
V1.38	Fixed	Fix for Force Fader clearing in GPI. Debounced switch inputs.
V1.37	Fixed	Fix for GPI length is longer loaded from config.
V1.36	Changed	Fader Interlock added options. GPO Monitor Select Remove Interlock mode. GPO settings initialised to enable more than 2 selections.
V1.33	Changed	Digital sync serial info incorporates Master mode(2) - SCi screen shows same as mixer.
V1.32	Fixed	Fix for Split Cue/PFL after factory defaults.
V1.31	Fixed	Fix for ACP:5 command.
V1.30	Fixed	Fix erased EEPROM on power up. Fix for release of force fader-up. Fix for channel 10 input B On. Fix MON command issue.
V1.29	Fixed	Mute Rev TB monitor output on live mic.
V1.27	Fixed	Fix GPI - HIGH/LOW functions wrong way round.
V1.26	Fixed	Fix Locking off of monitor/headphones when returning from Cue/PFL.
V1.25	New	New Button Mode - ON/OFF without Fader Interlock.
V1.24	Fixed	Fix Remote Mode RMA/RMB. Digital Output in Master Mode turns off Sync LED. Fixed Monitor select bug.
V1.23	Changed	Relocate Boot Vector Jumps.
V1.22	Fixed	Fix tracking of MFM & Split button states.