

Firmware Updates

For more information, contact our team on - technical.support@sonifex.co.uk

DHY-04V Firmware Versions		
Version	Changes	Description
1.15_GSM / 1.23_Main	Alterations	Updated VoLTE GSM Module Firmware which must be updated before the main firmware
1.15_GSM / 1.23_Main	Alterations	Fixed: Caller Rx/Tx audio noisy with LE910 VoLTE module
1.21	Alterations	Updated network registration process for 4G
1.21	Alterations	Added specific network setup and registration for operators in Australia
1.20	Alterations	Fixed noise gate audio level bug
1.19	Alterations	Added support for new 4G GSM module